

WoodOil - Cleaning & Maintenance Guide

1. INTRODUCTION

- Dryden recommends annual maintenance inspections and soft washing to keep the building in optimum condition.
- In some circumstances, due to localised environmental conditions, soft washing will be required more regularly.
- Inspections help with the early identification of maintenance requirements and minor issues before they become large expensive problems.
- Recent changes to the Building Code mean most timber cladding manufacturers provide proprietary systems. These systems require not only the correct materials being supplied and installed but also that timber is correctly <u>maintained</u> to ensure the required durability is met. In addition to having a new build signed off, <u>there must be a</u> <u>maintenance programme in place</u> for timber cladding.
- When timber maintenance is neglected and poorly maintained defects can occur, which may result in extensive and avoidable damage to the durability of the timber.
- When the timber is maintained in a systematic way, warranties for the timber building systems are met.

Note: Dryden WoodOil is NOT recommended for decking or furniture applications, for these hardwearing surfaces, Dryden recommends Dryden OilStain. For further information please refer to the product data sheets.

2. PRODUCT MAINTENANCE RE-COATING REQUIREMENTS

When Dryden WoodOil 'Clear' is applied, timber in exposed environments will <u>weather naturally and silver over time</u>. This means that the natural timber colour will be maintained under covered areas while transitioning out to silver in exposed areas.

	Maintenance: 1 coat system		
Thicker timbers	Thicker Timbers will require its first maintenance coat up to <u>1 Year</u> from the completion of the initial coating system.		
up to 1 year	The shorter relative first maintenance cycle is due to the greater volume of timber requiring a greater amount of oil for protection and durability		



	Maintenance: 1 coat system
Dressed timber & darker colours up to 1 year	Dressed timber and darker colours require their first maintenance coat at up to <u>1 Year</u> from the completion of the initial coating system to allow more colour enhancement. This includes garage doors, and all external exposed timber joinery faces such as
Modified timbers (Acetylated, Thermally) up to 1 year	frames, sashes and doors. Modified Timbers (Acetylated, Thermally) will require their first maintenance coat up to <u>1</u> <u>Year</u> from the completion of the initial coating system. Modified timbers are timbers that have had a chemical structure change and become very dry. Lower moisture levels create more space within the timber for oil to migrate into and therefore the timber requires more oil than standard timbers. Subsequent maintenance coats may extend out depending on areas coated, exposure,
Exterior timber: Dryden WoodOil with Dryden Colourtone+ added – up to 2 years	timber type and grain. The first maintenance coat is determined by the quality of application of the first coating, building design, orientation to the sun, chosen colour, timber type and grain. The type of building, locality and weather conditions found in New Zealand means that in some cases recoating may be necessary within two years.
	 After appropriate initial coats, re-application of Dryden WoodOil with a Dryden Colourtone+ is <u>up to two years</u> to exposed faces. This coat may be extended given better quality environmental conditions including shading, e.g., soffits.
	Dryden does not recommend re-coating the entire building at the same time. Areas which are still in good condition will still have the appropriate levels of Dryden WoodOil for protection.
	Note: Dryden Colourtones that are faded or chalked but appear even and consistent (not patchy), must not be cleaned off (soft wash only). When WoodOil is reapplied over faded or chalking coating, the coating will be rejuvenated, extending the UV attributes and cosmetic life.
Exterior timber Dryden WoodOil 'Clear'- up to <u>3</u> <u>years</u> (high exposure	When Dryden WoodOil 'Clear' is re-coated over any silvered timber, it will wet the silver patina and look patchy. This patchiness will revert to the original appearance over time
areas maximum up to 2 years first maintenance coat)	For ongoing durability, only one coat of Dryden WoodOil 'Clear' should be applied <u>up to 3</u> <u>years</u> after the initial coating system. <u>Note: Maintenance requirements may extend out depending on the quality of application</u>
	of the first coating, building design, orientation to the sun, weather exposure, chosen colour, timber type, and grain.



3. DETERMINING THE CLEANING METHOD

Annual Inspection & Soft Wash:

To keep your timber protected and looking fresh it must be inspected and maintained regularly. This simply means an annual soft wash and inspection of the timber surface.

By inspecting the building at the same time as the annual soft wash you can pre-empt any maintenance that may or may not need attending to. Maintenance does not necessarily mean the whole building will require re-coating at one time. Generally, the building will require maintenance in sections (elevations) depending on the building design, exposure and orientation to the sun.

Soft Wash Prior To Maintenance (when carried out on time):

Dryden recommends soft water washing of the surface to remove surface contaminants such as dust and pollens in preparation for maintenance recoating.

After cleaning Dryden recommend one coat of Dryden WoodOil only.

Note: Dryden Colourtones that are faded or chalking but still even and consistent (not patchy), must not be cleaned off (soft wash only). When WoodOil is reapplied over faded or chalking coating, the coating will be rejuvenated extending UV attributes and cosmetic life.

Strong Wash prior to remedial work of Dryden WoodOil with Dryden Colourtone+ added (maintenance not carried out on time):

If for any reason maintenance has not been kept up with Dryden WoodOil with Dryden Colourtone+ added or where timbers have not been previously coated and are silvered, then a stronger wash using Dryden SurfaceCleaner is recommended prior to re-coating with Dryden WoodOil. Do not use bleach-based products.

After cleaning Dryden recommends one initial coat followed by a <u>second coat 3-6 months</u> after the first coat application, to allow more colour enhancement and UV protection.

Refer to the Dryden SurfaceCleaner Data Sheet for further cleaning information.

Maintaining a Silver Patina (Dryden WoodOil 'Clear'):

When maintenance soft washes have not been kept up and mould spores have become apparent within the timber's silvered patina.

Graffiti Stains:

When Dryden WoodOil coated timbers have been marked with graffiti.

4. PREPARATION PRIOR TO CLEANING

Stormwater Collection:

All down pipes must be disconnected when feeding into stormwater collection system, to prevent contamination of waterways. Follow all local body requirements.

Tank water collection drinking or gardening:

Disconnect all down pipes and thoroughly flush all gutters and roof areas prior to reconnecting.

5. CLEANING METHODS



	Annual Inspection & Soft Wash		
It is difficult to determine the condition of a finish when it's covered with layers of dirt, dust, pollen and other contaminants that will attract mould. It is necessary therefore to soft wash the building with clean water before starting a maintenance inspection.			
Soft Wash	A soft wash with clean water is <u>intended to clean like rainfall</u> . It is sufficient to remove most surface contaminants such as dirt, dust, pollen, and other environmental grime and is particularly important for areas where rain and wind cannot usually reach.		
	Equipment:		
	• Dryden recommend using hose pressure in combination with a rose head spray adaptor with a shower setting to rinse the building. By using this method there is less chance of damaging the Dryden WoodOil coating.		
	• Or use a water blaster set to the lowest possible pressure and wide fan nozzle to generate a spraying mist.		
	• This method is acceptable when the <u>spray mist</u> is not brought close to the surface <u>(no less</u> <u>than 1.5 to 2 metres)</u> and is used to rinse the surface only. Take care not to disturb the coating in good even condition. Do not direct too closely around door openings, window frames and other openings in the cladding.		
	Note: Never use pencil or turbo nozzles on water blasters when cleaning timber.		
	Method:		
	 Pre-soak the timber surface with a hose or water blaster and wait 5 minutes before rinsing <u>linearly along the timbers</u>. Work from the top to bottom along the lengths of timber with long sweeping motions in the direction of the grain, feathering on and off at the end of each sweep of the area to be cleaned. 		
	 When stubborn dirt and contaminates are present use a soft brush (such as car wash brush) and a mild detergent solution to carefully remove, trying not to remove the Dryder Colourtone+. 		
	Note: Dryden Colourtones that are faded or chalking but still even and consistent (not patchy), must not be cleaned off (soft wash only). When WoodOil is reapplied over faded or chalking coating, the coating will be rejuvenated extending UV attributes and cosmetic life.		
	If the chalky Dryden Colourtone+ is coming off during the wash process, then soften the cleaning method.		
	Note: When the building is coated with Dryden WoodOil 'Clear' and has a silvered patina, the soft wash cleaning process should only clean off contaminants, not the desired silvered patina look.		
	Note: When stubborn dirt and contaminates are present use a soft brush (such as a car wash brush on house cleaning brush) and a mild detergent solution to carefully remove the mark, whilst trying not to remove the Dryden Colourtone+ or disturb the silver patina.		

4 | Page



Inspecting	What are you looking for when inspecting:
	• Start at one corner of the building and be sure to look all the way around. Inspect each wall individually and do not try to inspect too much at a time. Begin by standing back away from the wall and looking for some of the more obvious signs of aging then have a close look and feel.
	• From a distance it is easier to see general patterns of wear and fading of the coating, especially on the northern and western walls, look closely for colour fade.
	• When up close, look in detail at what is happening to the timber surface and feel for any chalking of the colour.
	What needs recoating:
	• Dryden does not recommend re-coating the entire building as there could be areas which are still in good condition, we only recommend coating the walls that are displaying signs of colour fade, or started chalking, which are just signs of maintenance being required and is normal.
	• When chalking has been left too long, has weathered off and allowed the timber to silver, a strong wash will be required.
	Refer to Washing Prior To Remedial Work (Maintenance not carried out on time)

Soft Wash Prior To Maintenance (If carried out on time)

A soft wash with clean water is <u>intended to clean like rainfall</u>. It is sufficient to remove most surface contaminants such as dirt, dust, pollen, and other environmental grime and is particularly important for areas where rain and wind cannot usually reach.

After cleaning, Dryden recommends one coat of Dryden WoodOil only.

• Refer to the Dryden WoodOil Data Sheet for further coating information.

Where Dryden Colourtone+ is even and consistent in colour but is faded or chalky, these elevations should be considered for a Dryden WoodOil maintenance coat.

• Note: Dryden Colourtones that are faded or chalking but still even and consistent (not patchy), must not be cleaned off (soft wash only). When WoodOil is reapplied over faded or chalking coating, the coating will be rejuvenated extending UV attributes and cosmetic life.

Equipment:

- Using hose pressure in combination with a rose head spray adaptor with shower setting to rinse the building. By using this method there is less chance of damaging the Dryden WoodOil coating.
- Alternatively, use a water blaster set to the lowest possible pressure and wide fan nozzle to generate a spraying mist.
- This method is acceptable when the <u>spray mist</u> is not brought close to the surface (<u>no less than 1.5 to 2</u> <u>metres</u>) and is used to rinse the surface only. Take care not to disturb the coating in good even condition. Do not direct too closely around door openings, window frames and other openings in the cladding.

Note: Never use pencil or turbo nozzles on water blasters when cleaning timber.

Method:

- Pre-soak the timber surface with a hose or water blaster and wait 5 minutes before rinsing <u>linearly along the</u> <u>timbers</u>. Work from the top to bottom along the lengths of timber with long sweeping motions in the direction of the grain, feathering on and off at the end of each sweep of the area to be cleaned.
- When stubborn dirt and contaminates are present use a soft brush (such as a car wash brush) and a mild detergent solution to carefully remove, trying not to remove the Dryden Colourtone+.

Note: Dryden Colourtones that are faded or chalking but still even and consistent (not patchy), must not be cleaned off (soft wash only). When WoodOil is reapplied over faded or chalking coating, the coating will be rejuvenated extending UV attributes and cosmetic life.



If the chalky Dryden Colourtone+ is coming off during the wash process, then soften the cleaning method.

When stubborn dirt and grime is present use a soft brush (such as a car wash brush) and a mild detergent solution to carefully remove, trying not to remove the Dryden Colourtone+.

- Note: When the building is coated with Dryden WoodOil 'Clear' and has a silvered patina, the soft wash cleaning process should only clean off contaminants, not the desired silvered patina look.
- Note: When stubborn dirt and contaminates are present use a soft brush (such as a car wash brush or house cleaning brush) and a mild detergent solution to carefully remove the mark, whilst trying not to remove the Dryden Colourtone+ or disturb the silver patina.



Strong wash prior to remedial work of Dryden WoodOil with Dryden Colourtone + added (maintenance not carried out on time) – Page 1

If for any reason maintenance has not been kept up with Dryden WoodOil & Dryden Colourtone+ or where timbers have not been previously coated and are silvered, then a stronger wash using <u>Dryden SurfaceCleane</u>r will be required prior to re-coating with Dryden WoodOil.

- Do not use bleach-based products.
- Refer to the Dryden SurfaceCleaner Data Sheet for further information.

After cleaning Dryden recommend one initial coat followed by a <u>second coat 3-6 months</u> later, to allow more colour enhancement and UV protection.

• Refer to the Dryden WoodOil Data Sheet for further coating information.

The natural silvering starts when the Dryden Colourtone+ (timber UV protection) has become chalky and eroded away through weathering.

Note: Dryden WoodOil is still within the timber providing the protection the timber requires, the Dryden Colourtone+ is a sacrificial part of the coating system.

Preparation	 Evaluate the exterior timber to be cleaned and use the appropriate cleaning method and the pressure required to avoid damaging the timber. When water blasting around painted surfaces, make sure that any visible damage is repaired <u>before</u> cleaning. If painted surfaces are unsound, the cleaning may lift and remove loose paint. Cover nearby plants, ponds, and light fixtures. Sweep or brush away loose debris from the surfaces to be cleaned. Close windows, doors, and place towels on the inside of windowsills. Cover areas that need to be
	Note: When the timber is weathered and silvered all damaged timber cells, mould, and other contaminants must be cleaned from the timber surface.
Cleaning tools	 Water blaster or power washer (preferred method) Firm bristle brush or broom, scouring pad. (Use only synthetic <u>not metal</u> scouring pads) <u>Note: Never use pencil or turbo nozzles on water blasters when cleaning timber.</u> <u>Note: Water blasters are better used with low pressure and a high-water volume, 13 litres per minute plus are best.</u> When using a waster blaster ensure you are only cleaning and removing colour, dirt and silvered timber, from the surface of the timber and not damaging the actual timber



Strong wash prior to remedial work of Dryden WoodOil with Dryden Colourtone+ added (maintenance not carried out on time) – Page 2	
Application tools	 Dryden SurfaceCleaner applies easily and rapidly and can be applied by: General garden sprayer Large backpack sprayer Motorised spray system
Dilution rates	 Mixing ratio 10g SurfaceCleaner per Litre of clean water E.g.100g Dryden SurfaceCleaner per 10 litres of clean water <u>Note: Ten litres of made up solution will clean approximately 60-70 square metres of timber surface, depending on the porosity of the timber and environmental conditions when applying.</u>
Dryden SurfaceCleaner application	Clean timber in shade out of direct sunlight or on overcast days. Direct sun and warmth will evaporate the product and so will not remain active on the surface. Product application must be carried out either in shade or on an overcast day to prevent the product from drying during the cleaning process. Pour mixture into a garden sprayer, seal and pressurize or other chosen method. Ensure the sprayer is kept pressurized to keep a good stream flowing. Saturate surface to be cleaned beginning from the bottom and moving towards the top so that the solution runs back down onto itself. Leave Dryden SurfaceCleaner on the surface for 15 -20 minutes, keeping wet (re-apply solution if necessary). This allows the Dryden SurfaceCleaner to



Strong wash prior to remedial work of Dryden WoodOil with Dryden Colourtone+ added (maintenance not carried out on time) – Page 3		
Cleaning methods	Before cleaning any surface, test the cleaning method in an inconspicuous area to determine the optima spray pattern, scrubbing technique and distance of the water blaster from the timber surface to obtain the best cleaning results.	
	Always take care to ensure all run-off is collected and safely disposed of or water boomed off onto gardens or grassed areas.	
	Severely mould-affected surfaces may require multiple cleaning treatments.	
	The following methods should remove all silvered timber fibres and chalking Dryden Colourtone+ When carried out correctly, the timber surface should be back to an even natural look, ready for re- coating.	
	Firm bristle brush, Broom, or Scouring pad cleaning.	
	 After the Dryden SurfaceCleaner has soaked the surface for 15 -20 minutes, use a firm brush to systematically clean the boards linearly to remove dirt, contaminants and oxidized timber (weathered). 	
	• On exterior cladding always clean from the top down to the bottom. This allows dirty water and contaminates to run off.	
	 <u>Note: Use a duster brush or synthetic scouring pads, no metal scours to avoid iron</u> staining. 	



Strong	wash	prior to remedial work of Dryden WoodOil with Dryden Colourtone+ added (maintenance not carried out on time) – Page 4
Cleaning methods	•	 Water Blaster Cleaning (preferred method) After the Dryden SurfaceCleaner has soaked the surface for 15 -20 minutes, use a water blaster to remove the dirt and oxidants. Set the water blaster to a low pressure setting approximately 870-1200 psi and wide fan (nozzle) setting. Note: Never use pencil or turbo nozzles on water blasters when cleaning timber.
		 On exterior cladding always work from top to bottom, this allows dirty water and contaminants to run off. Always clean timber linearly, in direction of the grain Keep the water blaster nozzle at a consistent distance from the timber surface and pressure levels at a level that avoids damaging the timber.
		 Clean the full length of the timber (do not stop mid-section. Clean timber to a natural break) going backwards and forward, <u>feathering on and off</u> at the end of each stroke overlapping slightly. <u>Note: Never leave the (water blasters) concentrated spray of pressurized water stationary in one spot at any time, especially when transitioning from left to right or vice versa of each cleaning stroke.</u>
		 This <u>will</u> result in 'water pressure cleaning lines' markings on the timber surface, which will show when recoating. <u>Always feather pressurized water</u> on and off to avoid markings. After cleaning with Dryden SurfaceCleaner always rinse off ensuring all cleaning residue is
		removed.



Strong wash prior to remedial work of Dryden WoodOil with Dryden Colourtone+ added (maintenance not carried out on time) – Page 5		
Inspection (once dry)	Once the timber has dried inspect your work. The appearance of timber changes as it dries, small imperfections can often go unnoticed when the timber is wet. The timber cladding should have no 'water pressure cleaning lines' from incorrect feathering on and off. The surface should be consistent with no areas unwashed, as when re-coating, faults may show.	
Remaining Dull Timber, Stains and Blemishes	After cleaning, timbers may have a dull appearance or have cosmetic stains and blemishes. Dryden LiquidTimberClean is an effective specialist cleaning product which can be used to freshen and brighten dulled timber and will help to improve any cosmetic staining and blemishes. Refer Dryden LiquidTimberClean data sheet for further information.	
Prior to coating	Once dry remove loose raised fibres (denib) using a 3M griddle scrubber or synthetic scorer pad, <u>not</u> <u>metal</u> .	
	Gently brush linearly along the length of the board to remove loose fibres. Ensure an even look and finish. Refer Dryden WoodOil data sheet for further coating information.	

6. MAINTAINING A SILVER PATINA (DRYDEN WOODOIL "CLEAR")

If for any reason maintenance Soft Washes have not been kept up and mould spores have become apparent within the timbers silvered patina, Dryden recommends using a product which will selectively kill mould and lichen on the exterior timber surface over an extended period.

Then over time, the weathering process will allow the dead growths to naturally erode away without damaging the silver patina.

• Note: Do not use bleach-based products.



7. GRAFFITI STAINS

When Dryden WoodOil coated timbers have been marked with graffiti, a careful light wash on the area with a water blaster on a wide fan setting may be all that is required.

If after cleaning stubborn graffiti is still present, apply a small amount of paint stripper to the affected area (once timber is dry) and follow the manufacturers procedures as per their data sheet.

Once dry after cleaning re-apply Dryden WoodOil (same colour as previously) to the affected area.

8. DRYDEN WOODOIL RE-COATING

For all re-coating requirements refer Dryden WoodOil Data Sheet.

9. PERSONAL PROTECTION EQUIPMENT (PPE) PRECAUTIONS

Always wear appropriate PPE such as protective gloves, eye protection and face protection.

When spraying or in case of inadequate ventilation wear respiratory protection.

Wash skin thoroughly after handling with hot soapy water.

Refer to the Dryden WoodOil Safety Data Sheet for detailed information.

10. FURTHER INFORMATION

The responsibility for products sold is subject to our standard terms and conditions.

For additional information on Dryden WoodOil, refer to the Dryden WoodOil Cleaning Guide and Dryden WoodOil SDS (Safety Data Sheet).

For further information:



Contact 0800 379 336 or

Click on www.Dryden.co.nz

The sale of this product is subject to our standard conditions of sale.

Dryden is a registered trademark of DuluxGroup (New Zealand) Pty Ltd.

13 Page

